SEL SCHWEITZER ENGINEERING LABORATORIES, INC.

www.selinc.com

INSTRUCTIONS FOR CREATING PART NUMBERS

- 1. Select one code (in bold) from each column. List option codes in the order that they appear in the column.
- 2. Follow your usual process to issue a purchase order, or complete a specification for standards.

OVERHEAD AUTORANGER (AR-OH)			
AutoRANGER	Permanent Time-Out	Momentary Time-Out	Overhead Designation
AR	4 4 hrs	- 0 0 hrs	-0H
	8 8 hrs	-4 4 hrs	
		-8 8 hrs	
		-16 16 hrs*	
		-24 24 hrs*	

^{*}Extended time-out may affect battery life. Please consult SEL.

Example Part Number: AR4-8-0H