

POWERTECH LABS INC.

Test Report

**PERFORMANCE TESTING OF
AUTORANGER FAULTED CIRCUIT INDICATOR**


Tested in Accordance with:
ANSI/IEEE Std. 495-1986

Overall Test Result: PASS


PROJECTS 15739-23-00, 15702-43-00, and 16539-23-00
REPORT NO. 15739-05-REP1

Prepared for:
**Schweitzer Engineering Laboratories,
E.O. Schweitzer Manufacturing Division**


Prepared by:

Chris Morton, P.Eng.
Senior Engineer
Power System Technologies
Signature 
Date 10 OCT 2006



Martin Colwell
Senior Technologist
Chemistry
Signature 
Date 10 Oct 2006

Reviewed by:

Dr. J. Bruce Neilson, P.Eng.
Principal Engineer
Power System Technologies
Signature 
Date 10 Oct 06

